



ICOP TECHNOLOGY INC.,
昭營科技股份有限公司

RS485 transmission trouble

Please add 620 Ohm resistors on Pull-up/Pull-down. For more detail information, please visit: http://www.interfacebus.com/Design_Connector_RS485.html.

For more technical support, please visit <http://www.dmp.com.tw/tech/> or mail to tech@dmp.com.tw
